

WA-I- 513 Brick House

Mid-20th century

Hagerstown Vicinity

Private

The Brick House is a one story three by two-bay house on a concrete block foundation. It has a gable roof with dormers on the main facade. The brick is laid in stretcher bond.

Magi No.

DOE yes no

Maryland Historical Trust

State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic Brick house

and/or common

2. Location

street & number east side of Rt. 65, .14 mile south of the intersection of I-70 not for publicationcity, town Hagerstown X vicinity of congressional district sixthstate Maryland county Washington

3. Classification

Category	Ownership	Status	Present Use	
<u> </u> district	<u> </u> public	<u> </u> occupied	<u> </u> agriculture	<u> </u> museum
<u> </u> building(s)	<u> </u> private	<u> </u> unoccupied	<u> </u> commercial	<u> </u> park
<u> </u> structure	<u> </u> both	<u> </u> work in progress	<u> </u> educational	<u> </u> private residence
<u> </u> site	Public Acquisition	Accessible	<u> </u> entertainment	<u> </u> religious
<u> </u> object	<u> </u> in process	<u> </u> yes: restricted	<u> </u> government	<u> </u> scientific
	<u> </u> being considered	<u> </u> yes: unrestricted	<u> </u> industrial	<u> </u> transportation
	<u> </u> not applicable	<u> </u> no	<u> </u> military	<u> </u> other:

4. Owner of Property (give names and mailing addresses of all owners)

name

street & number telephone no.: city, town state and zip code

5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liber street & number Washington Street folio city, town Hagerstown state Maryland

6. Representation in Existing Historical Surveys

title date federal state county local depository for survey records city, town state

7. Description

Survey No. WA-I-~~493~~ 513

Condition

☐ excellent
☐ good
☐ fair

☐ deteriorated
☐ ruins
☐ unexposed

Check one

☐ unaltered
☐ altered

Check one

☐ original site
☐ moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The brick house is a one story three by two-bay house on a concrete block foundation. It has a gable roof with dormers on the main facade. The brick is laid in stretcher bond.

The property is located on the east side of Rt. 65, .14 mile south of the intersection of I-70. It is located in a group of buildings on $\frac{1}{4}$ to $\frac{1}{2}$ acre lots constructed from mid-20th century to the present time.

The main facade from this house has a central entrance with a white and green striped aluminum awning. Eight-over-one pane windows are located on each side of the central entrance. Gable dormers within six-over-six pane windows are located on the asphalt shingle covered roof. Each gable end contains two windows on the first floor and a small window in the half story. On the southernmost gable end is a concrete block flue projecting from the end of the building.

There are no significant outbuildings on the property.

8. Significance

Survey No. WA-I-~~493~~ 513

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: ☐ A ☐ B ☐ C ☐ D
and/or


Applicable Exception: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G

Level of Significance: ☐ national ☐ state ☐ local

Prepare both a summary paragraph of significance and a general statement of history and support.


Based on the MHT Survey Matrix, this is a minimal site due to its recent date of construction.


WA-I-513
 Brick House, site
 10515 Sharpsburg Pike (MD 65)
 Funkstown Quadrangle



1993-94 Aerial Photo

Tax Map 57, p. 155





1. Brick House WA-I-493 5/3
2. Washington County, Maryland
3. Joe Getty
4. May 1983
5. Maryland Hist. Trust, Annapolis, Md.
6. West Elevation; camera facing east
7. 1/1